

Ref. No.: 36/24/C

Date: 29.08.2024

STRUCTURAL ASSESMENT REPORT

Location: Vatsalya School, Sr.No. 16 Wadachiwadi, Undri Tal. Haveli, Dist Pune 411060.


Client : Rajiv Arora, Shree Sai Education Society, Undri, Pune.

Reference : Site visit on 27.01.2020 along with Mr. Amit Dunghav.

Description: Existing school building is **Ground + One floor** RCC frame structure and MS Structural Roofing sheet. The approximate size of building is 700 Sq.m and floor height is 3m at each floor. RCC Columns and beams are 230, 300 mm wide. Brick walls are 230 and 150 mm thick BBM and resting on RCC beams at plinth and slab level.

I hereby certify that I have inspected the premises, the plans of which have been approved by the Chief Engineer vide his letter no. Dated , and examined the various parts including the foundations. I am of the opinion that all the works of engineering construction in the premises are structurally sound and that their stability will not be endangered by their use as a part of the School Building.

Yours Sincerely,
For Matrix Engineers

Seal of the Firm

Authorized Signatory
Sachin Yadav
Proprietor



Structural Consultant, Chartered Engineer
PMC LIC. No. – 349/MIE, M-147533-3
(Note: - Letter Valid up to 1 year from issuing date)